

Tri – Form R

Releasing agent for mould and shutter

Description

Tri -Form R is a ready for use chemicals releasing agent for all types of moulds and shatters faces, where is blended from selective refined mineral oils and other special additives.



Uses

Tri -Form R applied on mould and shutter faces prior to casting concrete In order to achieve a clean release after removal of form work and to achieve concrete has a smooth uniform finish with reduced incidence of blow holes.

Advantages

- Easy application.
- High quality of concrete finishes surfaces.
- Protection of form work from steel corrosion and early aging.
- Easy release of moulds. Shatters without any damages.

Technical Data @°25c

DISCRETIONS	VALUE
Appearance	Brownish yellow liquid
Density	0.83 ± 0.02 kg/L
Rate of use	20 M ² / L for wood surfaces 55 M ² / L for steel and plastic surfaces (Depending on the porosity of mould, shatters surfaces)

Directions for use

The new mould and shutter no preparation of the surface is required.

The used form work should be clean and dry before application, with any residues of rust or concrete removed.

Mix the product well before use.

Apply the product by spray, brush, roller or sponge on the surfaces of mould and shutter One coat is enough in case of non pores surfaces, but in case surfaces with high porosity may be need to apply another coat.



Factory & Head Office:

6 October City - 4th Industrial Zone - Al Oula Industrial Zone Plot No.: 14 Tel.: (002) 011 195 48267 - Sales: (002) 010 007 88817 - (002) 011 184 87597 Technical Support Call : (002) 011 184 87880 - Email: sales@tichem-eg.com www.trichem-eg.com



Tri – Form R

Releasing agent for mould and shutter

Cleaning

All tools should be cleaned with thinner immediately after use.

Package

Tri -Form R is available in containers (20 & 200 & 1000)

Shelf Life

Has a shelf life of 12 month stored in dry and cool place

Storage

The product is flammable. Do not expose to naked flames or to others source of ignition.

Health and Safety

Application should be carried out in well ventilated place.

Gloves, protective clothing and eye goggles should be worn during application. Skin contaminations should be immediately cleaned with soap and plenty of water. Don't use solvent.

If the material is splashed into the eyes, they should be immediately washed with water and then report to an eye specialist

Do not eat or smoke during application.



page 2 of 2



Factory & Head Office:

6 October City - 4th Industrial Zone - Al Oula Industrial Zone Plot No.: 14 Tel.: (002) 011 195 48267 - Sales: (002) 010 007 88817 - (002) 011 184 87597 Technical Support Call : (002) 011 184 87880 - Email: sales@tichem-eg.com www.trichem-eg.com